

Recordable Incidents Summary Report: Environmental Management Plan (EMP) - NT Exploration Permit 187 Beetaloo Sub-Basin 2019 Seismic Program.

The following information has been compiled to satisfy the reporting requirements for recordable incidents under Part 3, Division 1, Regulation 35 of the Petroleum (Environment) Regulations for the Beetaloo Sub-Basin 2019 Civils and Seismic Program Environmental Management Plan (EMP). This is the first reporting period post approval of the EMP and covers the period of October 2019 to December 2019.

SUMMARY OF RECORDABLE INCIDENTS UNDER SECTION 35 PETROLRUM (ENVIRONMENT) REGULATIONS QUARTERLY REPORT FOR PERIOD 10/2019 TO 12/2019							
ENVIRONMENT MANAGEMENT PLAN – Exploration Permit 187 Beetaloo Sub-Basin 2019 Civils and Seismic Program (EMP)							
Incident date (dd/mm/yy)	Area / Location	Incident Summary	Actual Consequence (From Risk Assessment)	Corrective Actions	Relevant Environment Performance Standard	Effect on Relevant Environmental Outcome	Other Regulator Notification.
29/10/2019	Seismic Line 4	One small scrub fire ignited by the tracks of bulldozer and immediately extinguished	1 - Slightly. (Negligible financial consequences; localised and short-term impact to an area, plants or animals of environmental value. Readily treated)	<ul style="list-style-type: none"> - Watercart driver spotted the smoke and immediately got out of the vehicle - Put out the fire with the vehicles fitted fire extinguisher. - Future actions: <ul style="list-style-type: none"> o Watercart to be driven at enough distance behind the dozer or grader. 	Bushfire prevention: <ul style="list-style-type: none"> - Fire contained - Minimise risk of causing bushfires from activities, - Minimise impact on environmental habitat 	NIL – Very small grass area burnt, causing none harm to environmental habitats nor to cultural heritage and sacred sites	DENR have been notified
15/10/19	Seismic line 6	Small grass fibres from the dozer tracks were being sucked into the engine bay (assisted by the tail wind). Grass ignited on exhaust manifold/turbo and embers fell to grass build up on belly plate	1 - Slightly. (Negligible financial consequences; localised and short-term impact to an area, plants or	<ul style="list-style-type: none"> - shutdown immediately - used fire extinguisher to put out fire/had - extra assistance from grader operator was requested 	Asset integrity – Fire contained	NA	N/A

**SUMMARY OF RECORDABLE INCIDENTS UNDER SECTION 35 PETROLRUM (ENVIRONMENT) REGULATIONS
QUARTERLY REPORT FOR PERIOD 10/2019 TO 12/2019**

ENVIRONMENT MANAGEMENT PLAN – Exploration Permit 187 Beetaloo Sub-Basin 2019 Civils and Seismic Program (EMP)

Incident date (dd/mm/yy)	Area / Location	Incident Summary	Actual Consequence (From Risk Assessment)	Corrective Actions	Relevant Environment Performance Standard	Effect on Relevant Environmental Outcome	Other Regulator Notification.
			animals of environmental value. Readily treated)	<ul style="list-style-type: none"> - fire extinguisher used to ensure incident fully contained. - Machinery put out of service for the time and repair parts ordered. Further actions: <ul style="list-style-type: none"> - blow/clean out engine bay regularly as required - During red alert days(>40) or clearing heavy grass inspect and blow/clean out engine bay every hr (or more frequently as required) 			
30/10/19	Line 65 Station 1334	Minor back injury due to slipping on loose gravel. Operator slid out landing on his back	1 - Slightly. Readily treated	<ul style="list-style-type: none"> - Person received help from operators around him and was taken to local clinic for a check-up. - Precautionary light duties for 3 days. 	No site injuries. Discussions on toolbox for people to be more careful and look for better access.	No Environmental harm	N/A